STATE OF ILLINOIS EDP Date
ENVIRONMENTAL PROTECTION AGENCY OBSERVATION REPORT - L P C F C O 5 5 C
$(\overline{1})^{(\overline{8})(\overline{9})}$
SANGAMON County Springfier / BUERKETT 2 (315+) Site Code 16782516
Time: From $\underline{l} \bigcirc : \underline{l} \subseteq \underline{A} \underline{m}$ Photos Taken: Yes (#) No (X) Region \underline{C} Date $\underline{f} \supseteq \underline{f} \supseteq \underline$
To 11:35 Am Site Open: Yes (X) No () Letter Sent (Yes or No) No
Samples Taken: Yes () No (\times) Groundwater () Surface () Other () Inspector (27) (29)
Interviewed MERLE BUERKETT Weather COOL, CLOUDY
Previous Inspection 10-01-84 Previous Correspondence 16-15-84
OPERATIONAL STATUS: TYPE OF OPERATION: AUTHORIZATION:
Operating () Sanitary Landfill () Transfer () E.P.A. Permit () Temporarily Closed () Random Dump () Dump () Variance () Closed and Covered () Other () Ouantity Received Daily (1-6) Board Order () Other ()
None (5)
GENERAL REMARKS (37
RKH JOHNSON, DLPC/FOS, accompanied me on this
investigation which was prompted by a telephone call from
Merle Buerkett. Mr. Buerkett called to say there was a
tanker truck at his landfill carrying an Junmanifested
load of liquid waste. Mr. Buerke'H Osaid he had refused
permission to the truck driver to dispose of the
waste. Mr. JoHNSON and I arrived at the site to
determine the identity of the waste, we met John Denny and Larry Sidener of Waste
Me met John Denny and Larry Sidewer of waste
Age a local septic wast hauling firm and IEPA special wask hauler #1276. Mrk Denny said the waste was water pumped from an excavation at the main post office at 600 E. Monroe in Springfield. The
Special wast hauter "1216, Mry Denny said the waste
main not office at 600 E. Mangat in Social Field The
haste was a brown, muddy water having a slight
odor. Mr. Sidener said approximately 2250 gallons
were in the tanker. This amount was said to be
about 2/3 the tanker capacity, we accompanied
Mr. Denny to the Post Office to observe the
excavation. In the alley south of the Post Office
the observed on correcting tell 30 K/5 x/0 deep 10
hole where a nearby 10,000 gallon tank had begin in
hole where a nearby 10,000 gallon tank had been 10,000 gallon tank had been 10,000 the excavation 11 532-0309 17/82)

EDP Date ____



DATE: 12-12-94 TO: DIVISION FILE FROM: D. C. SANSON _____ Information only SUBJECT: 16782516 SANGAMON CO. contained No standing water other than in an 8" pipe placed in the bottom to serve as a sump. a concrete slab was said to be under the gravel in the bottom of the excavation, Mr. Denny said the tank that was removed had contained fuel oil. He said about 2200 gallons of fuel oil were lost from the tank about 4 years ago No trace of fuel oil was visible in the excavation. Water in the 8" pipe had an odor of fuel oil. Mr. Denny seid Big Three Corp. of P.O. BOX 164 WINDHAM, NEW HAMPSHIRE 63087 603-893-4048 was the contractor hired by the Post Office to remove the old tank and install a New Upon returning to the landfill I made arrangements to have a special wask permit (attacked for the tanker of fuel oil contaminated water issued) to Buerkett landfill, and a generator number issued to Big Three Corp, I assisted Mr. Denny in completing the incomplete manifest originally brought to the landfill. Subsequent to the inspection I recommended to the Big Three representative in Spfled. That they obtain a special waste permit for the Tuel oil contaminated contaminated gravel remaining in the excavation (See attached). JAN 29 193
PERA 90A 6/75 IET LOUPO